

# Fusion Installer Release Notes

---

VERSION: 3.6; BUILD DATE: 2015-05-05

## Bug Fix

---

- Packet loss in the **Ping Test** window was not calculated correctly. It always looked like there was 0% loss. This is fixed.